

Performance Automotive Inc.
 3239 Phoenixville Pk.
 Malvern, PA. 19355
 Phone: 610-695-9545 Fax: 610-695-9098

INVOICE

12258

Org. Est. # 026380

INVOICE

Work Completed : 03/23/2021

Date: 03/24/2021

LBI Limited - Reade Etherington

4500 Worth St
 Philadelphia, PA 19124
 Cellular 610-357-5095

1972 Porsche - 911 - 2.8 Carbs

Lic # :

Odometer In : 86825

Odometer Out : 86828

VIN # :

Part Description	Qty	Sale	Ext	Labor Description	Ext
NGK Spark Plugs	12.00	10.53	126.36	Compression and leakage test up to 1989 3.2 Carrera,	269.94
Crush washer	2.00	1.00	2.00	Check MFI fuel pump timing	
Brake Clean	2.00	4.79	9.58	Leakage Test #1-2% #2-3% #3-3% #4-3% #5-3% #6-4%	
911 Oil Filter 72-94	1.00	24.13	24.13	Compression Test #1-155 #2-160 #3-165 #4-165 #5-165	
Penn Grade #1 SAE 20/50	11.00	14.00	154.00	#6-165	
Dot4 brake fluid	3.00	5.50	16.50	General check over and list service needs	134.97
Sump plate cover with drain plug	1.00	168.95	168.95	Shipping on plugs	38.65
Brake bleeder dust cap	4.00	5.12	20.48	Oil Change Service	134.97
Alternator shim	3.00	4.95	14.85	Brakes LF- 12 RF- 12	
Shop Supplies			47.63	LR- 12 RR- 12	
				Tires LF- 3 RF- 3	
				LR- 3 RR- 3	
				Adjust Alternator belt and add proper amount of	67.49
				adjustment shims	
				Adjust clutch	67.49
				DOT-4Brake Flush	121.47
				Replace sump cover	80.98
				Remove front bumper for customer to refinish and bag	134.97
				up hardware in front trunk	
				[Recommendations]	
				Make sure that both Ignition switches near the key area are pulled	
				down at all times when running or starting	
				Oil level gauge is not accurate / Please use dipstick and check	
				when fully warmed up	
				Tires have a small amount of dry rot cracks on sidewalls (not	
				uncommon for vintage race tires)	

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Labor:	1,012.28
Parts:	584.48
Sublet:	38.65
Sub:	1,635.41
Tax:	98.12
Total:	\$1,733.53
Bal Due:	\$1,733.53

Vehicle Received: 3/23/2021

Customer Number : 5042

Signature _____ Date _____