

Performance Automotive Inc.
 3239 Phoenixville Pk.
 Malvern, PA. 19355
 Phone: 610-695-9545 Fax: 610-695-9098

INVOICE
12840

Org. Est. # 026555

INVOICE

Printed Date: 02/01/2022 **Work Completed: 10/21/2021**

LBI Limited - Reade Etherington
 4500 Worth St
 Philadelphia, PA 19124
 Cellular 610-357-5095

1994 Porsche - 911 Carrera 2 - 3.8 Litre
 Lic # : Odometer In : 24480
 Odometer Out : 24485
 VIN # : WP0ZZZ992 RS398097

Part Description	Qty	Sale	Ext	Labor Description	Ext
Spark Plug FR5DTC (Bosch)	12.00	7.30	87.60	Leakage and compression testing / replace spark	404.91
Fuel Filter	1.00	46.62	46.62	plugs	
Gear Oil GEAR 300 75W90 1L	4.00	24.37	97.48	#1- 2% #2- 2% #3- 3% #4- 2% #5- 3% #6- 2%	
Valve Cover Gasket-Upper	3.00	10.18	30.54	#1- 205 psi #2- 210 psi #3- 205 psi #4- 205 psi #5- 210 psi #6-	
Brake Fluid RBF 660 Racing fluid	2.00	44.91	89.82	205psi	
Window winder cover	2.00	45.32	90.64	Clean vehicle for delivery	n/c
Window winder	2.00	56.89	113.78	Replace fuel filter	67.49
Screws	2.00	12.43	24.86	Brakes L/F 9 R/F 9 L/R 10 R/R 10 Tires L/F 4 R/F 4	
Crush washer	2.00	1.00	2.00	L/R 4 R/R 4	
Brake Clean	2.00	4.79	9.58	(new Pirelli slicks)	
oil filter small	1.00	20.22	20.22	ABS light stays on Diagnose and repair power supply	269.94
large oil filter	1.00	20.25	20.25	to ABS Fuse terminal	
crush rings	2.00	1.50	3.00	Adjust alternator belt	26.99
Mobil 1 Oil	10.00	12.68	126.80	Replace shift shaft seal	161.96
Brake Clean	1.00	4.79	4.79	Drivers side seat belt hardware is bottomed out and bent need to straighten and repair reinforce	67.49
Rear spoiler rocker switch	1.00	78.61	78.61	Oil seeping on RS of engine Replace Bank 2 upper	134.97
Shop Supplies			78.58	valve cover gaskets	
				Window crank handles	33.74
				Drain Gearbox oil and replace with new GL5 Spec oil	121.47
				replace crush washers and torque	
				Change oil and filters	168.71
				DOT-4 Brake Flush & ABS Pump Flush(with racing	134.97
				fluid)	
				Fabricate new front hood pin lanyards	67.49
				Fuel for vehicle	45.00
				Install spoiler switch	67.49

Performance Automotive Inc.
 3239 Phoenixville Pk.
 Malvern, PA. 19355
 Phone: 610-695-9545 Fax: 610-695-9098

INVOICE

12840

Org. Est. # 026555

INVOICE

Printed Date: 02/01/2022

Work Completed: 10/21/2021

LBI Limited - Reade Etherington

4500 Worth St
 Philadelphia, PA 19124
 Cellular 610-357-5095

1994 Porsche - 911 Carrera 2 - 3.8 Litre

Lic # :

VIN # : WP0ZZZ992 **RS398097**

Odometer In : 24480

Odometer Out : 24485

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Org. Estimate 2,859.66 Revisions 0.00 Current Estimate 2,859.66

Labor:	1,727.62
Parts:	925.17
Sublet:	45.00
SubTotal:	2,697.79
Tax:	161.87
Total:	2,859.66
Bal Due:	\$0.00

[Payments - Check (#AUTO Deposit) - \$2,859.66]

Vehicle Received: 10/21/2021

Customer Number : 5042

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Signature _____ Date _____