

INVOICE

Printed Date: 10/18/2021 Work Completed: 10/18/2021

LBI Limited - Reade Etherington

4500 Worth St
 Philadelphia, PA 19124
 Cellular 610-357-5095

1994 Porsche - 911 Carrera 2 - 3.8 Litre

Lic # :

Odometer In : 0

VIN # : WP0ZZZ992 **RS398097**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Left bumper trim	1.00	136.00	136.00	Sublet paint and body work for decklid and front bumper parts Install rear decklid assembly, Install new control unit for rear retractable tail. Repair damaged rear electrical harness Remove front and rear aero body work and replace with non aero body work pieces Core charge on control unit not with vehicle	750.00
Right bumper trim	1.00	136.00	136.00		809.82
Panel nut	8.00	1.05	8.40		234.83
Left rocker cover	1.00	284.00	284.00		
Right rocker panel	1.00	375.64	375.64		
Bracket (left)	1.00	18.65	18.65		
Bracket (right)	1.00	18.65	18.65		
Rocker bracket	2.00	6.88	13.76		
Trim bolt	1.00	5.42	5.42		
Plastic nut	8.00	2.64	21.12		
Used decklid assembly	1.00	1,200.00	1,200.00		
Rear spoiler control unit <CORE>	1.00	525.36	525.36		
Shop Supplies			136.13		

Body work for Non Acid Conversion

Org. Estimate 0.00 Revisions 4,954.21 Current Estimate 4,954.21

Revision # 1, Previous Estimate Amount: 0.00, Additional Cost: 4954.21, Revised Estimate: 4954.21, Parts: \$2743.00 Labor: \$809.82 Sublet: \$984.83
 Taxes & Fees: \$416.56 Authorized by - Etherington, Reade, Date - 10/18/2021, Time - 2:01PM, Initiated By - Shop, Written By - McDonald, Paul,
 Phone Number - Cellular: 610-357-5095

Labor:	809.82
Parts:	2,879.13
Sublet:	984.83
SubTotal:	4,673.78
Tax:	280.43
Total:	4,954.21
Bal Due:	\$4,954.21

[Payments -]

Vehicle Received: 10/18/2021

Customer Number : 5042

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Signature _____ Date _____