

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
5/21/2019	17656

PAID
05/21/2019

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		49,323
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Troubleshoot and diagnose - Check engine light on			110.00	110.00T
	Scan diagnostics - Clear fault codes				
5	Free up rusted and seized turbo actuator rods			110.00	550.00T
	Clear fault codes				
	Road Test and rescan - No faults have returned			0.00	0.00T
0.4	Replace right front marker light bulb			110.00	44.00T
	Subtotal - Labor				704.00
	Right front bulb			3.20	3.20T
	Subtotal - Parts				3.20
	Subtotal				707.20
	Sales Tax			6.00%	42.43
We appreciate your business.				Total	\$749.63

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
10/14/2019	18013

PAID
10/15/2019

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		53,444
QUANTITY	DESCRIPTION			RATE	AMOUNT
1.3	Change oil and filter.			110.00	143.00T
	Reset service light				
1	Replace brake fluid and bleed brake system			110.00	110.00T
6.1	Replace spark plugs			110.00	671.00T
0.3	Replace cabin filter			110.00	33.00T
0.4	Replace air filter			110.00	44.00T
0.9	Replace drive belt			110.00	99.00T
	Subtotal - Labor				1,100.00
	Cabin air filter			73.81	73.81T
	Oil filter - NO CHARGE			0.00	0.00T
6	Spark plug			16.65	99.90T
	Air filter			56.10	56.10T
	Drive belt			115.09	115.09T
	Subtotal - Parts				344.90
8.5	Synthetic Oil			13.11	111.44T
	MOA oil additive			12.65	12.65T
	1 pint dot 4 brake fluid.			25.29	25.29T
	Subtotal - Gas, Oil, Grease				149.38
	Subtotal				1,594.28
	Sales Tax			6.00%	95.66
We appreciate your business.				Total	\$1,689.94

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
6/10/2019	17695

PAID
06/12/2019

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		49,765
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Perform Pennsylvania State Inspection			25.00	25.00T
	Insp. Specifications. Tires 8/32 Brakes L/F 9/B			0.00	0.00T
	R/R 8/B Sticker#AI9 - 5623969				
	Subtotal - Labor				25.00
	State Emission Test			65.00	65.00T
	Subtotal - Outside Service				65.00
	Subtotal				90.00
	Sales Tax			6.00%	5.40
We appreciate your business.				Total	\$95.40

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
11/11/2019	18091

PAID
11/13/2019

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		54,287
QUANTITY	DESCRIPTION			RATE	AMOUNT
1	Troubleshoot and diagnose - Check engine light on Scan diagnostics - Clear fault codes			110.00	110.00T
1	Found excessive leaf build up in air filter housing Clean out and road test - All systems good			110.00	110.00T
4.5	Fault in air bag system for passenger front sensor Replace front passenger sensor to include removal of front bumper			110.00	495.00T
	Road Test			0.00	0.00T
	Subtotal - Labor				715.00
	Front sensor			129.78	129.78T
	Subtotal - Parts				129.78
	Subtotal				844.78
	Sales Tax			6.00%	50.69
We appreciate your business.				Total	\$895.47

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
12/6/2019	18144

PAID
12/06/2019

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		54,694
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Troubleshoot and diagnose - Check engine light on			110.00	110.00T
	Scan diagnostics - Clear fault codes				
4	Replace bank 2 upstream oxygen sensor			110.00	440.00T
	Road Test x 2 = 120 miles			0.00	0.00T
	Rescan for codes no faults stored				
4	Mount and balance snow tire/s.			38.00	152.00T
	Reset TPM				
	Subtotal - Labor				702.00
	Oxygen sensor			303.13	303.13T
	Subtotal - Parts				303.13
	Gas fill-up			60.00	60.00T
	Subtotal - Gas, Oil, Grease				60.00
	Subtotal				1,065.13
	Sales Tax			6.00%	63.91
We appreciate your business.				Total	\$1,129.04

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
2/24/2020	18353

PAID
02/25/2020

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		56,473
QUANTITY	DESCRIPTION			RATE	AMOUNT
1.3	Change oil and filter. Reset service light			110.00	143.00T
1.5	Install oxygen sensor spacer			110.00	165.00T
	Subtotal - Labor				308.00
	Oil filter - NO CHARGE			0.00	0.00T
	Oxygen sensor spacer			70.00	70.00T
	Subtotal - Parts				70.00
8.5	Synthetic Oil			13.11	111.44T
	MOA oil additive			12.65	12.65T
1	Washer fluid / Deicer			5.75	5.75T
	Subtotal - Gas, Oil, Grease				129.84
	Subtotal				507.84
	Sales Tax			6.00%	30.47
We appreciate your business.				Total	\$538.31

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
6/26/2020	18650

PAID
06/29/2020

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		58,070

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Perform Pennsylvania State Inspection	25.00	25.00T
	Insp. Specifications. Tires 7/32 Brakes L/F 8/B R/R 7/B Sticker#AI0 -05483617	0.00	0.00T
1.3	Change oil and filter. Reset service light Reattach rear window wiper - NO CHARGE	110.00	143.00T
4	Mount and balance summer tires	38.00	152.00T
1	Troubleshoot and diagnose - Check engine light on for fault codes - Code Bank 2 sensor 1 - Oxygen sensor slow response Scan diagnostics - Clear fault codes	110.00	110.00T
1	Perform drive cycle to pass emissions x3	110.00	110.00T
3.5	Replace left side air mass meter Reposition oxygen sensor Scan and clear for faults Perform drive cycle to pass emissions	110.00	385.00T
		110.00	110.00T

We appreciate your business.	Total
------------------------------	--------------

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
6/26/2020	18650

PAID
06/29/2020

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		58,070
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Next recommended service due at 80,000 miles for cabin air filter and air filter			0.00	0.00T
	Spark plug replacement is needed every 40,000 miles or every 4 years. Done - 53,000 miles on 10/2019				
	Synthetic oil change recommended every 4000 miles or yearly				
	Subtotal - Labor				1,035.00
	Oil filter - NO CHARGE			0.00	0.00T
	Air mass meter -LIST PRICE \$1154.26			650.00	650.00T
	Subtotal - Parts				650.00
8.5	Synthetic Oil			13.47	114.50T
	MOA oil additive			12.65	12.65T
	Gas fill-up			50.00	50.00T
	Subtotal - Gas, Oil, Grease				177.15
	State Emission Test			65.00	65.00T
	Subtotal - Outside Service				65.00
	Subtotal				1,927.15
	Sales Tax			6.00%	115.63
We appreciate your business.				Total	\$2,042.78

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
12/11/2020	19134

PAID
12/29/2020

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		59,371
QUANTITY	DESCRIPTION			RATE	AMOUNT
1.5	Road side service			110.00	165.00T
	Repair fuse box connection for hood release				
	Drop off customers Audi and pickup Porsche				
4	Mount and balance winter tires.			35.00	140.00T
	Reset TPMS				
2	Install trickle charger pig tail connection			110.00	220.00T
	Next recommended service due at 60,000 miles			0.00	0.00T
	for cabin air filter, drive belt, and differential fluid				
	Synthetic oil change recommended every 4000 miles or yearly				
	Subtotal - Labor				525.00
	Subtotal				525.00
	Sales Tax			6.00%	31.50
We appreciate your business.				Total	\$556.50

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
6/16/2021	19511

PAID
06/17/2021

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		59,692

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Perform Pennsylvania State Inspection	25.00	25.00T
	Insp. Specifications. Tires 7/32 Brakes L/F 8/B R/R 5/B Sticker#AI1 -05517502	0.00	0.00T
1.3	Oil change	110.00	143.00T
4	Remove wheels and tires and install summer wheels and tires	35.00	140.00T
5	Replace driver and passenger side front lower control arms	110.00	550.00T
	Perform 4 wheel alignment	220.00	220.00T
	Fill chip in windshield	70.00	70.00T
	Subtotal - Labor		1,148.00
	Oil filter	24.94	24.94T
2	Front lower control arm	564.16	1,128.32T
2	Nut	2.90	5.80T
2	Nut	3.14	6.28T
2	Lock nut	2.90	5.80T
2	Bolt	5.65	11.30T
4	Pan head screw	5.39	21.56T
4	Hexagon bolt	2.57	10.28T
2	Hexagon bolt	3.87	7.74T
2	Hex head bolt	5.65	11.30T

We appreciate your business.	Total
------------------------------	--------------

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
6/16/2021	19511

PAID
06/17/2021

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		59,692
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Shipping & Handling			61.40	61.40T
	Windshield repair kit			10.00	10.00T
	Subtotal - Parts				1,304.72
8.5	Synthetic Oil			13.47	114.50T
1	MOA oil additive			19.40	19.40T
	Subtotal - Gas, Oil, Grease				133.90
	State Emission Test			65.00	65.00T
	Subtotal - Outside Service				65.00
	Subtotal				2,651.62
	Sales Tax			6.00%	159.10
We appreciate your business.				Total	\$2,810.72

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
9/15/2021	19759

PAID
09/16/2021

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		59,853
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Perform safety check and report any concern/s to owner			110.00	110.00T
	Brakes, suspension, lights, wipers, electrical equipment, tires, exhaust, belts, and hoses checked - Findings include				
	Scan/Clear codes in all modules and reset services			110.00	110.00T
	Fault codes P1252 Bank 1 boost pressure adjuster sluggish signal implausible				
	P1372 Valve lift control, Bank 1 below limit value				
2	Attempt to adjust turbo linkages for bank 1			110.00	220.00T
	Actuator seized and needs to be replaced				
	Reassemble customer will return to have work completed				
0	Replace bank 1 turbo actuator - Ten hours to perform the job			110.00	0.00T
	Subtotal - Labor				440.00
0	Bank 1 turbo actuator - Part number 997-605-315-05			1,234.91	0.00T
0	Linkage rod for actuator - Part number 997-123-123-70			57.95	0.00T
	Subtotal - Parts				0.00
We appreciate your business.				Total	

**Christopher Radbill's Automotive Repair,
LLC**

906 Old Fernhill Road, Unit 6
West Chester, PA 19380
610-701-9401

REPAIR ORDER

DATE	R.O. #
9/15/2021	19759

PAID
09/16/2021

BILL TO

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
PC00305	Porsche	911	2007		59,853
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Subtotal				440.00
	Sales Tax			6.00%	26.40
We appreciate your business.				Total	\$466.40

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I ALSO HEREBY AGREE TO PAY FOR ANY AND ALL COURT FEES AND ATTORNEYS ASSOCIATED WITH ANY LEGAL ACTION TAKEN IN RESPONSE OR IN CONJUNCTION WITH WORK BEING PERFORMED ON MY CAR. I CERTIFY THAT I AM AWARE THAT NO WARRANTY WILL BE HONORED ON MY CAR FOR ANY WORK NOT FULLY COMPLETED OR PAID FOR.